



PROCESSING INSTRUCTIONS

slideprotect indoor 2 m² (Item No. 47110102)

slideprotect indoor 5 m² (Item No. 47110105)

1. Cleaning and preparation of the surface to be coated:

Removal of all lime residues: Moisten the surface with warm water. Apply lime remover evenly, let it act for a short time (about 5-10 min.), thoroughly scrub the surface, rinse with cold water.

Removal of all dirt and soap residues: Rinse with cold water. Wipe the surface dry and keep it absolutely dry.

Limit the surface to be coated with conventional painter's tape.

2. Applying slideprotect indoor:

For absorbent or non-smooth surfaces, a primer must be applied before coating. Otherwise, the slideprotect coating will penetrate the material and will not be able to perform its function.

Once the surface is dry, continue with the coating. Please observe the drying time for the primer as per the respective manufacturer's instructions.

Please shake the contents well for at least **2 minutes** before use.

Do not pour the contents directly onto the surface to be coated, but use a coating tray and apply with a lacquer roller (standard short pile, not fine foam roller).

Dip the lacquer roller into the coating material; roll off excess material until the roller is evenly saturated and no longer drips.

Begin coating. Always work from the center of the area outwards. First, coat the surface evenly and thinly in one direction, then distribute the already applied material again with the roller offset by 90°; roll the surface again offset by 90° (without pressure on the roller).

The slideprotect coating is slightly milky when applied and will become transparent during drying.

Wipe off any drips immediately with lukewarm water.

Please remove the tape immediately after coating.

Unused slideprotect coating can be returned to the bottle. If the opened bottle is well sealed it can be kept for about 3 months at cellar temperature.

3. Drying of the coating:

After 24 hours of drying time, your surface is ready for use again. (optimal conditions: temperature > 20°C and good ventilation!)

Mechanical cleaning should not be performed until one week after drying.

Should you have any questions or suggestions, we are happy to help.

Please contact us by email: anfrage@rutschfrei.de